

CFS Fibreglass United Downs Industrial Park Redruth Cornwall TR16 5HY

Tel **01209 821028** | Fax **01209 822191**Web www.cfsnet.co.uk | Email sales@cfsnet.co.uk

MATERIAL SAFETY DATA SHEET

Product

BRASS POWDER

Protective Measures

Keep containers totally closed. Avoid naked

flames, water or heat.

Normal protective clothing such as safety glasses

and gloves should be worn.

Ensure adequate ventilation.

Toxicity

Non-toxic and non-hazardous

Waste

Remove according to local regulations.

Accident / Fire

Use dry sand for spillage and exclude all air. Do not use water or chlorinated hydrocarbons

such as carbon tetrachloride.

Storage

Moderate stable temperature.

<u>Dust</u>

Fine particles can ignite under certain conditions and, therefore, avoid dust clouds.

Classified under SHW 830 - Dust Explosions in Factories - HMSO - as Group B and, therefore, does not propagate flame in the test apparatus.

General

Copper - based alloys can be irritating to skin. Therefore washing in water is recommended. With eyes, wash immediately and seek medical

attention if necessary.

Other Information

In accordance with Chemicals (Hazard information

and packaging for supply) Regulations 2002